


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-175	Smoke	7/20/2009	ADS/TM	S13AA_066MH	Dry	Yes	660.95



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-175	Smoke	7/20/2009	ADS/TM	S13AA_066MH	Dry	Yes	660.95

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S13AA_066G1	S13AA_066MH	S13AA_020MH	195.157	10
S13AA_073G1	S13AA_073MH	S13AA_066MH	187.856	8
S13AA_074G1	S13AA_074DE	S13AA_075MH	107.999	6
S13AA_075G1	S13AA_075MH	S13AA_073MH	169.941	8

Observations & Photos

Obs_ID S1028-175-OB01
Address 2805 Mosher St.
Status Private
Source Cleanout

Location Yard - front
Nearest MH S13AA_073MH

Comments Smoke from cleanout (missing cap) in front yard. 2805 Mosher St.

Obs_ID S1028-175-OB01
Address 2805 Mosher St.
Status Private
Source Cleanout

Location Yard - front
Nearest MH S13AA_073MH

Comments Smoke from cleanout (missing cap) in front yard. 2805 Mosher St.



Picture \S1028-175-OB01-P01.jpg

Comments Front of house, 2805 Mosher St.



Picture \S1028-175-OB01-P02.jpg

Comments Front of house (location view), 2805 Mosher St.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-175	Smoke	7/20/2009	ADS/TM	S13AA_066MH	Dry	Yes	660.95

Obs_ID S1028-175-OB02

Address 2813 Mosher St

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13AA_073MH

Comments Smoke from cleanout (broken cap) in front yard. 2813 Mosher St.



Picture \S1028-175-OB02-P01.jpg

Comments Front of house (flag in background), 2813 Mosher St.

Obs_ID S1028-175-OB03

Address 2811 Mosher St.

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13AA_073MH

Comments Smoke from cleanout (missing cap) in front yard. 2811 Mosher St.



Picture \S1028-175-OB03-P01.jpg

Comments Front of house (flag in foreground), 2811 Mosher St.

Obs_ID S1028-175-OB03

Address 2811 Mosher St.

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13AA_073MH

Comments Smoke from cleanout (missing cap) in front yard. 2811 Mosher St.



Picture \S1028-175-OB03-P02.jpg

Comments Front yard, 2811 Mosher St.

Obs_ID S1028-175-OB04

Address 931 Poplar Grove St.

Status Private

Source Cleanout

Location Yard - side

Nearest MH S13AA_075MH

Comments Smoke from above-grade cleanout (broken cap) in side yard. 931 Poplar Grove St.



Picture \S1028-175-OB04-P01.jpg

Comments Side yard, 931 Poplar Grove St.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-175	Smoke	7/20/2009	ADS/TM	S13AA_066MH	Dry	Yes	660.95

Obs_ID S1028-175-OB05

Address 2823 Mosher St.

Status Private

Source Cleanout

Location Yard - side

Nearest MH S13AA_075MH

Comments Smoke from cleanout (missing cap) in side yard of 2823 Mosher St.

Obs_ID S1028-175-OB06

Address Mosher St. & Dukeland St.

Status Public

Source Catch Basin

Location Curb

Nearest MH S13AA_066MH

Comments Smoke from catch basin along curb on southeast corner of Mosher St. & Dukeland St.



Picture \S1028-175-OB05-P01.jpg

Comments Side yard, 2823 Mosher St.



Picture \S1028-175-OB06-P01.jpg

Comments Mosher St. & Dukeland St. looking north